

Figure 6 failed to include reference to inlet slots 63. The inlet slots 63 are erroneously referenced as reference numeral 61. A red-lined copy of Figure 6, with the proposed amendment thereto as well as a substitute drawing for Figure 6 properly reflecting the amendment are enclosed.

IN THE SPECIFICATION

1. Replace the complete paragraphs:
 - a. beginning at page 15, line 10, through page 16, line 22, replace with the substitute paragraphs as indicated in the enclosed marked-up version.
 - b. beginning at page 24, lines 11 through 20, replace with substitute paragraph as indicated in the enclosed marked-up version.
2. A 'clean version' for each of the actions made above, and as indicated in the respective marked-up version, is attached hereto.

IN THE CLAIMS

1. Amend Claims 63 and 74 as indicated in the enclosed 'marked-up' version.
2. Add Claims 75 through 87 as indicated in the enclosed 'marked-up' version'.